

HDR | 1001 SW 5th Avenue | Suite 1900 | Portland, Oregon 97204 | 503.423.3800 THA | 733 SW Oak Street | Suite 100 | Portland, Oregon 97205 | 503.227.1254




UO LISB

Lewis Integrative Science Building

Preliminary Schematic Design August 20, 2009

EX-100

SITE SURVEY OF EXISTING CONDITIONS SITE NORTHWEST QUADRANT



HDR | 1001 SW 5th Avenue | Suite 1900 | Portland, Oregon 97204 | 503.423.3800 THA | 733 SW Oak Street | Suite 100 | Portland, Oregon 97205 | 503.227.1254



UO LISB


Lewis Integrative Science Building

Preliminary Schematic Design August 20, 2009

survey of existing conditions dwg

EX-200

SITE SURVEY OF EXISTING CONDITIONS SITE NORTHEAST QUADRANT



HDR | 1001 SW 5th Avenue | Suite 1900 | Portland, Oregon 97204 | 503.423.3800 THA | 733 SW Oak Street | Suite 100 | Portland, Oregon 97205 | 503.227.1254




UO LISB

Lewis Integrative Science Building

Preliminary Schematic Design August 20, 2009

EX-300

SITE SURVEY OF EXISTING CONDITIONS SITE SOUTHEAST QUADRANT



HDR | 1001 SW 5th Avenue | Suite 1900 | Portland, Oregon 97204 | 503.423.3800 THA | 733 SW Oak Street | Suite 100 | Portland, Oregon 97205 | 503.227.1254



UO LISB

Lewis Integrative Science Building

Preliminary Schematic Design August 20, 2009

EX-400

SITE SURVEY OF EXISTING CONDITIONS SITE SOUTHWEST QUADRANT